

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

D:\SAS Homepage\home(V2.0).HTM-Microsoft Internet Explorer

Address

TSID

Full Report
☐

Small Report
☐

German

Welcome to the
Service Assistance System (SAS)

TSID: 1-2P21EM

Date/Time: 2/1/03, 9:14:04 p.m. CET

Vehicle data:

VIN WDB211086ABCDEF12

Mileage: 123 456 km

Vehicle condition:

ESP information light.....flashing

High beam driver's side.....defective

Motor oil level.....minimum reached

Defects found:

ESP (electric stability program)

C0815.....Rpm sensor interrupted

C4711.....Steering angle sensor
not initialized

SRS (airbag)

B1234.....Line to belt lock front left
has short circuit to ground

B9876.....Coding for side airbag rear
not correct

FIG. 7




FIG. 8